



Sanitary Quality of Surface Water During Base-Flow Conditions in the Municipality of Caguas, Puerto Rico, 2014-15: A Comparison With Results From a Similar 1997-99 Study

By
Jesús Rodríguez-Martínez and Senén Guzmán-Ríos
2017

Any use of trade, product, or firm names in this publication is for descriptive purposes only and does not imply endorsement by the U.S. Government.

This map was printed on an electronic plotter directly from digital files. Dimensional calibration may vary between electronic plotters and between X and Y directions on the same plotter, and paper may change size due to atmospheric conditions; therefore, scale and proportions may not be true on plots of this map.

For sale by U.S. Geological Survey, Information Services, Box 25288, Federal Center, Denver, CO 80225, 1-888-ASK-USGS

Suggested citation: Rodríguez-Martínez, Jesús, and Guzmán-Ríos, Senén, 2017, Sanitary quality of surface water during base-flow conditions in the Municipality of Caguas, Puerto Rico, 2014-15: A comparison with results from a similar 1997-99 study, U.S. Geological Survey Scientific Investigations Report 2017-5045, p. https://doi.org/10.3133/sir/20175045